


O33408

2 parts on this sheet
Mild Steel,0.125
GX 10K — 120" x 60" sheet
No warnings in the file.

PROGRAM CALLS (sub — part @ rot x copies)
075442 pdlv-plate

@0 x2




033409

3 parts on this sheet
Mild Steel,0.125
GX 10K — 120" x 60" sheet
No warnings in the file.

PROGRAM CALLS (sub — part @ rot x copies)


075442	pdlv-plate	@0	x1
075443	pdlv-tag	@0	x1
075444	pdlv-tag	@180	x1



pdlv-plate — 50.000" x 40.000", 1 hole

HOLES (X,Y from part lower-left)

id	size"	X"	Y"
A	ø6.000	25.000	20.000



pdlv-tag — 30.000" x 20.000", 0 holes

